



Worktop hole opening size:

Standard Version: X = Length -5

Y = Width -5